(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Muscatine County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary	Trench sanitary landfill			Daily cover fo landfill	r
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
41: Sparta	95	Very limited Seepage Too Sandy	1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00
41B: Sparta	95	Very limited Seepage Too Sandy	1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00
41D: Sparta	95	Very limited Seepage Too Sandy Slope	1.00 1.00 0.16	Very limited Seepage Slope	1.00	Very limited Too Sandy Seepage Slope	1.00 1.00 0.16
51B: Vesser	100	Very limited Flooding Depth to saturated zone Too clayey	1.00	Very limited Flooding Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00
63B: Chelsea	95	Very limited Seepage Too Sandy	1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00
63C: Chelsea	95	Very limited Seepage Too Sandy	1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00
63D: Chelsea	100	Very limited Seepage Too Sandy Slope	1.00 1.00 0.63	Very limited Seepage Slope	1.00	Very limited Too Sandy Seepage Slope	1.00 1.00 0.63
63E: Chelsea	95	Very limited Seepage Too Sandy Slope	1.00 1.00 1.00	Very limited Seepage Slope	1.00	Very limited Too Sandy Seepage Slope	1.00 1.00 1.00

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Muscatine County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary				Daily cover fo	r
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
63G: Chelsea	95	Very limited Slope Seepage Too Sandy	1.00 1.00 1.00	Very limited Slope Seepage	1.00	Very limited Slope Too Sandy Seepage	1.00 1.00 1.00
65D2: Lindley	100	Somewhat limited Too clayey Slope	0.50	Somewhat limited Slope	0.16	Somewhat limited Too clayey Slope	0.50 0.16
65E2: Lindley	100	Very limited Slope Too clayey	1.00	Very limited Slope	1.00	Very limited Slope Too clayey	1.00
65F: Lindley	90	Very limited Slope Too clayey	1.00	Very limited Slope	1.00	Very limited Slope Too clayey	1.00
65G: Lindley	90	Very limited Slope Too clayey	1.00	Very limited Slope	1.00	Very limited Slope Too clayey	1.00
118: Garwin	95	Very limited Depth to saturated zone Too clayey	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00
119: Muscatine	90	Very limited Depth to saturated zone Too clayey	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey Depth to saturated zone	0.50
120B: Tama	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
120B2: Tama	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Muscatine County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitar landfill	Trench sanitary landfill			Daily cover fo landfill	r
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
120C: Tama	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
120C2: Tama	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
120C3: Tama	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
120D2: Tama	100	Somewhat limited Slope Too clayey	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63
120D3: Tama	100	Somewhat limited Slope Too clayey	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63
122: Sperry	100	Very limited Depth to saturated zone Too clayey	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00
133: Colo	95	Very limited Flooding	1.00	Very limited Flooding	1.00	Very limited Depth to saturated zone	1.00
		Depth to saturated zone Too clayey	0.50	Depth to saturated zone	1.00	Too clayey	0.50
133B: Colo	95	Very limited Flooding	1.00	Very limited Flooding	1.00	Very limited Depth to saturated zone	1.00
		Depth to saturated zone Too clayey	1.00	Depth to saturated zone	1.00	Too clayey	0.50

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Muscatine County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitar landfill	У	Area sanitary landfill		Daily cover fo landfill	r
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
135B: Coland	100	Very limited Flooding Depth to saturated zone Seepage Too clayey	1.00 1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00
136: Ankeny	100	Very limited Seepage	1.00	Very limited Seepage	1.00	Somewhat limited Seepage	0.50
139: Perks	90	Very limited Flooding Seepage Too Sandy	1.00 1.00 1.00	Very limited Flooding Seepage	1.00	Very limited Too Sandy Seepage	1.00
141: Watseka	95	Very limited Depth to saturated zone Seepage Too Sandy	1.00	Very limited Depth to saturated zone Seepage	1.00	Very limited Too Sandy Seepage Depth to saturated zone	1.00
152: Marshan	90	Very limited Depth to saturated zone Seepage Too Sandy	1.00	Very limited Depth to saturated zone Seepage	1.00	Very limited Depth to saturated zone Too Sandy Seepage	1.00
160: Walford	95	Very limited Depth to saturated zone Too clayey	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00
162B: Downs	95	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
162C: Downs	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Muscatine County, Iowa

Map symbol and soil name	Pct. of map unit	landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
162C2: Downs	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
162C3: Downs	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
162D2: Downs	100	Somewhat limited Slope Too clayey	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63
162D3: Downs	100	Somewhat limited Slope Too clayey	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63
163B: Fayette	95	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
163C: Fayette	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
163C2: Fayette	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
163D: Fayette	100	Somewhat limited Slope Too clayey	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63
163D2: Fayette	100	Somewhat limited Slope Too clayey	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63
163E: Fayette	95	Very limited Slope Too clayey	1.00	Very limited Slope	1.00	Very limited Slope Too clayey	1.00

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Muscatine County, Iowa

Map symbol and soil name	Pct. of map unit	landfill		Area sanitary landfill		Daily cover fo landfill	or
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
163E2: Fayette	100	Very limited Slope Too clayey	1.00	Very limited Slope	1.00	Very limited Slope Too clayey	1.00
163F: Fayette	90	Very limited Slope Too clayey	1.00	Very limited Slope	1.00	Very limited Slope Too clayey	1.00
163G: Fayette	100	Very limited Slope Too clayey	1.00	Very limited Slope	1.00	Very limited Slope Too clayey	1.00
164: Traer	95	Very limited Depth to saturated zone Too clayey	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00
165: Stronghurst	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Depth to saturated zone	0.86
173: Hoopeston	95	Very limited Depth to saturated zone Seepage Too Sandy	1.00	Very limited Depth to saturated zone Seepage	1.00	Very limited Too Sandy Seepage Depth to saturated zone	1.00 1.00 0.86
174: Bolan	90	Very limited Seepage Too Sandy	1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy	1.00
174B: Bolan	95	Very limited Seepage Too Sandy	1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy	1.00

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Muscatine County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitar	У	Area sanitary landfill		Daily cover fo landfill	r
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
175: Dickinson	95	Very limited Seepage Too Sandy	1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy	1.00
175B: Dickinson	100	Very limited Seepage Too Sandy	1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy	1.00
175C: Dickinson	100	Very limited Seepage Too Sandy	1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy	1.00
179D2: Gara	95	Somewhat limited Slope Too clayey	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63
179F: Gara	95	Very limited Slope Too clayey	1.00	Very limited Slope	1.00	Very limited Slope Too clayey	1.00
212: Kennebec	95	Very limited Flooding Depth to saturated zone	1.00	Very limited Flooding Depth to saturated zone	1.00	Not limited	
249B: Zwingle	100	Very limited Depth to saturated zone Too clayey	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Hard to compact Too clayey	1.00 1.00 0.50
291: Atterberry	90	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Depth to saturated zone	0.86
291B: Atterberry	90	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Depth to saturated zone	0.86

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Muscatine County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitar	Y	Area sanitary landfill		Daily cover fo landfill	or
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
293G: Chelsea	50	Very limited Slope Seepage Too Sandy	1.00 1.00 1.00	Very limited Slope Seepage	1.00	Very limited Slope Seepage Too Sandy	1.00 1.00 0.50
Fayette	35	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
313G: Gosport	90	Very limited Depth to saturated zone	1.00	Very limited Slope	1.00	Very limited Depth to bedrock	1.00
		Slope Depth to bedrock Too clayey	1.00	Depth to saturated zone Depth to bedrock	1.00	Slope Too clayey Hard to compact Depth to saturated zone	1.00 1.00 1.00 0.68
315: Aquolls	90	Not rated		Not rated		Not rated	
352B: Whittier	95	Very limited Seepage Too clayey	1.00	Very limited Seepage	1.00	Somewhat limited Too clayey	0.50
352C: Whittier	95	Very limited Seepage Too clayey	1.00	Very limited Seepage	1.00	Somewhat limited Too clayey	0.50
352C2: Whittier	95	Very limited Seepage Too clayey	1.00	Very limited Seepage	1.00	Somewhat limited Too clayey	0.50
352D2: Whittier	95	Very limited Seepage Slope Too clayey	1.00 0.63 0.50	Very limited Seepage Slope	1.00	Somewhat limited Slope Too clayey	0.63

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Muscatine County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary	У	Area sanitary landfill		Daily cover fo landfill	r
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
450B: Pillot	95	Very limited Too Sandy Seepage	1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy	1.00
450C2: Pillot	95	Very limited Too Sandy Seepage	1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy	1.00
467: Radford	98	Very limited Flooding	1.00		1.00	Somewhat limited Depth to saturated zone	0.86
		Depth to saturated zone	1.00	Depth to saturated zone	1.00		
467B: Radford	98	Very limited Flooding	1.00	Very limited Flooding	1.00	Somewhat limited Depth to saturated zone	0.86
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Buttinged 2011c	
479G: Gale	90	Very limited Slope Depth to bedrock Seepage Too clayey	1.00 1.00 1.00 0.50	Very limited Slope Seepage Depth to bedrock	1.00	Very limited Depth to bedrock Slope Too clayey	1.00 1.00 0.50
480C2: Orwood	90	Not limited		Not limited		Not limited	
480D2: Orwood	100	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63
480F2: Orwood	100	Very limited Slope		Very limited Slope	1.00	Very limited Slope	1.00
481D2: Russell	95	Somewhat limited Slope	0.37	Somewhat limited Slope	0.37	Somewhat limited Slope	0.37

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Muscatine County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill	У	Area sanitary landfill		Daily cover fo landfill	r
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
481E2: Russell	100	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
485: Spillville	95	Very limited Flooding Depth to saturated zone Seepage	1.00	Very limited Flooding Depth to saturated zone	1.00	Not limited	
485B: Spillville	95	Very limited Depth to saturated zone Seepage	1.00	Very limited Depth to saturated zone	1.00	Not limited	
488C2: Newvienna	90	Very limited Depth to saturated zone Too clayey	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey Depth to saturated zone	0.50
488C3: Newvienna	100	Very limited Depth to saturated zone Too clayey	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey Depth to saturated zone	0.50
488D2: Newvienna	95	Very limited Depth to saturated zone Slope Too clayey	1.00 0.63 0.50	Very limited Depth to saturated zone Slope	1.00	Somewhat limited Slope Too clayey Depth to saturated zone	0.63
488D3: Newvienna	100	Very limited Depth to saturated zone Slope Too clayey	1.00 0.63 0.50	Very limited Depth to saturated zone Slope	1.00	Somewhat limited Slope Too clayey Depth to saturated zone	0.63

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Muscatine County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitar landfill	У	Area sanitary landfill		Daily cover fo landfill	or
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
490: Caneek	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
539: Perks	85	Very limited Flooding Seepage Too Sandy	1.00 1.00 1.00	Very limited Flooding Seepage	1.00	Very limited Seepage Too Sandy	1.00
566B: Moingona	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Not limited	
566C: Moingona	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Not limited	
567B: Moingona Variant	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Depth to saturated zone	0.09
623C2: Rozetta	100	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Not limited	
623D2: Rozetta	100	Very limited Depth to saturated zone Slope	1.00	Very limited Depth to saturated zone Slope	1.00	Somewhat limited Slope	0.63
653: Tuskeego	95	Very limited Depth to saturated zone Seepage Too clayey	1.00 1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Muscatine County, Iowa

Map symbol and soil name			У	Area sanitary landfill		Daily cover fo landfill	or
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
680G:							
Lindley	50	Very limited Slope Too clayey	1.00	Very limited Slope	1.00	Very limited Slope Too clayey	1.00
Douds	20	Very limited Depth to saturated zone	1.00	Very limited Slope	1.00	Very limited Slope	1.00
		Slope	1.00	Depth to	1.00	Too Sandy	0.50
		Too Sandy Seepage	1.00	saturated zone Seepage	1.00	Seepage	0.21
Orwood	20	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
684: Elrick	90	Very limited Seepage Too Sandy Flooding	1.00 1.00 0.40	Very limited Seepage Flooding	1.00	Very limited Too Sandy Seepage	1.00
727: Udolpho	100	Very limited Depth to saturated zone Seepage Too Sandy	1.00	Very limited Depth to saturated zone Seepage	1.00	Very limited Depth to saturated zone Too Sandy Seepage	1.00
753B: Thebes	95	Very limited Seepage Too Sandy	1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy	1.00
753C: Thebes	95	Very limited Seepage Too Sandy	1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy	1.00
753C2: Thebes	95	Very limited Seepage Too Sandy	1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy	1.00

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Muscatine County, Iowa

Map symbol and soil name	Pct. of map unit	landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
753D2: Thebes	95	Very limited Seepage Too Sandy Slope	1.00 1.00 0.63	Very limited Seepage Slope	1.00	Very limited Seepage Slope Too Sandy	1.00 0.63 0.50
759: Fruitfield	95	Very limited Seepage Too Sandy	1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00
759B: Fruitfield	100	Very limited Seepage Too Sandy	1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00
763E3: Exette	100	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
763F3: Exette	100	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
771C2: Waubeek	95	Not limited		Not limited		Not limited	
771D2: Waubeek	100	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63
793: Bertrand	100	Very limited Seepage Too clayey	1.00	Not limited		Somewhat limited Too clayey	0.50
826: Rowley	90	Very limited Depth to saturated zone Seepage	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Depth to saturated zone	0.86
916B: Downs	100	Very limited Seepage Too clayey	1.00	Not limited		Somewhat limited Too clayey	0.50

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Muscatine County, Iowa

Map symbol and soil name	Pct. of map unit	landfill	Area sanitary landfill		Daily cover for landfill		
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
916B2: Downs	95	Very limited Seepage Too clayey	1.00	Not limited		Somewhat limited Too clayey	0.50
916C: Downs	100	Very limited Seepage Too clayey	1.00	Not limited		Somewhat limited Too clayey	0.50
916C2: Downs	95	Very limited Seepage Too clayey	1.00	Not limited		Somewhat limited Too clayey	0.50
917B: Fayette	95	Very limited Seepage Too clayey	1.00	Not limited		Somewhat limited Too clayey	0.50
917C: Fayette	100	Very limited Seepage Too clayey	1.00	Not limited		Somewhat limited Too clayey	0.50
917C2: Fayette	95	Very limited Seepage Too clayey	1.00	Not limited		Somewhat limited Too clayey	0.50
917D2: Fayette	95	Very limited Seepage Slope Too clayey	1.00 0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63
920B: Tama	95	Very limited Seepage Too clayey	1.00	Not limited		Somewhat limited Too clayey	0.50
920B2: Tama	95	Very limited Seepage Too clayey	1.00	Not limited		Somewhat limited Too clayey	0.50

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Muscatine County, Iowa

Map symbol and soil name	Pct. of map unit	landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
920C:							
Tama	- 100	Very limited Seepage Too clayey	1.00	Not limited		Somewhat limited Too clayey	0.50
920C2: Tama	- 95	Very limited Seepage Too clayey	1.00	Not limited		Somewhat limited Too clayey	0.50
920C3: Tama	- 95	Very limited Seepage Too clayey	1.00	Not limited		Somewhat limited Too clayey	0.50
925: Toolesboro	- 100	Very limited Depth to saturated zone Seepage	1.00	Very limited Depth to saturated zone Seepage	1.00	Very limited Depth to saturated zone Seepage	1.00
930: Orion	- 95	Very limited Flooding Depth to saturated zone	1.00	Very limited Flooding Depth to saturated zone	1.00	Somewhat limited Depth to saturated zone	0.86
960: Shaffton	- 95	Very limited Flooding Depth to saturated zone	1.00	Very limited Flooding Depth to saturated zone	1.00	Somewhat limited Depth to saturated zone	0.09
961: Ambraw	- 98	Seepage Very limited Flooding	1.00	Very limited Flooding	1.00	Very limited Depth to saturated zone	1.00
		Depth to saturated zone Seepage	1.00	Depth to saturated zone Seepage	1.00		

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Muscatine County, Iowa

Map symbol and soil name	Pct. of map unit	landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
963: Elvers	90	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 1.00	Very limited Flooding Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
977: Richwood	100	Very limited Seepage	1.00	Not limited		Not limited	
977B2: Richwood	100	Very limited Seepage	1.00	Not limited		Not limited	
1043: Bremer	95	Very limited Depth to saturated zone Seepage Too clayey	1.00 1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00
1212: Kennebec	85	Very limited Flooding Depth to saturated zone	1.00	Very limited Flooding Depth to saturated zone	1.00	Not limited	
1490: Caneek	98	Very limited Flooding Depth to saturated zone	1.00	Very limited Flooding Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
1520: Coppock	95	Very limited Depth to saturated zone Seepage Too clayey	1.00 1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Muscatine County, Iowa

Map symbol and soil name	Pct. of map unit	of landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
1621: Houghton	100	Very limited Depth to saturated zone Content of organic matter Seepage	1.00	Very limited Depth to saturated zone Seepage	1.00	Very limited Depth to saturated zone Content of organic matter Seepage	1.00
1926: Canoe	90	Very limited Depth to saturated zone Seepage	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Depth to saturated zone	0.09
2221: Palms	95	Very limited Depth to saturated zone Content of organic matter Seepage	1.00	Very limited Depth to saturated zone Seepage	1.00	Very limited Depth to saturated zone Content of organic matter Seepage	1.00 1.00 0.16
2226: Elrin	90	Very limited Depth to saturated zone Seepage Too Sandy	1.00	Very limited Depth to saturated zone Seepage	1.00	Very limited Too Sandy Seepage	1.00
2490: Caneek Variant	95	Very limited Depth to saturated zone Too Sandy	1.00	Very limited Depth to saturated zone Seepage	1.00	Very limited Too Sandy Seepage	1.00
2587: Dolbee	100	Very limited Depth to saturated zone Seepage Too clayey	1.00 1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Muscatine County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitar landfill	У	Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
2636: Radford	50	Very limited Flooding	1.00	Very limited Flooding	1.00	Somewhat limited Depth to	0.86
		Depth to saturated zone Too clayey	1.00	Depth to saturated zone	1.00	saturated zone Too clayey	0.50
Hanlon	30	Very limited Flooding Depth to saturated zone	1.00	Very limited Flooding Depth to saturated zone	1.00	Somewhat limited Seepage	0.50
3133: Colo	100	Seepage Very limited Depth to saturated zone	1.00	Seepage Very limited	1.00	Very limited Depth to saturated zone	1.00
3134: Zook	90	Too clayey Very limited Depth to saturated zone Too clayey	1.00	Very limited Depth to saturated zone	1.00	Too clayey Very limited Depth to saturated zone Too clayey	1.00
3135: Coland	95	Very limited Depth to saturated zone Seepage Too clayey	1.00 1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00
3960: Shaffton	95	Very limited Depth to saturated zone Seepage	1.00	Very limited Depth to saturated zone Seepage	1.00	Very limited Seepage Depth to	1.00
3961: Ambraw	95			Very limited		saturated zone Very limited Depth to saturated zone	1.00

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Muscatine County, Iowa

Map symbol and soil name	Pct. of map unit	landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
4160: Walford	75	Very limited Depth to saturated zone Too clayey	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00
Urban Land	25	Not rated		Not rated		Not rated	
4162C: Downs Urban Land		Not limited Not rated		Not limited Not rated		Not limited Not rated	
4163D: Fayette	50	Somewhat limited Slope Too clayey	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63
Urban Land	45	Not rated		Not rated		Not rated	
4636: Radford	50	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00	Somewhat limited Depth to saturated zone Too clayey	0.86
Urban Land	45	Not rated		Not rated		Not rated	
4759: Fruitfield	45	Very limited Seepage Too Sandy	1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00
Urban Land	45	Not rated		Not rated		Not rated	

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Muscatine County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
4960: Shaffton	50	Very limited Depth to saturated zone Seepage Too Sandy	1.00	Very limited Depth to saturated zone Seepage	1.00	Very limited Seepage Too Sandy Depth to saturated zone	1.00
Urban Land	40	Not rated		Not rated		Not rated	
4977B: Richwood	50	Very limited Seepage	1.00	Not limited		Not limited	
Urban Land	40	Not rated		Not rated		Not rated	
5010: Pits	100	Not rated		Not rated		Not rated	
5040: Orthents	100	Not rated		Not rated		Not rated	
W: Water	100	Not rated		Not rated		Not rated	